


A117.1 2003 errata

28 August, 2008

- Page 18: In Figure 404.2.3.1(a) the dimension string on the right side should read “455” for the metric instead of “445.”
- Page 20: In Figure 404.2.3.4(a) the dimension string on the upper right side should read “455” for the metric instead of “445.”
- Page 27: In Figure 407.2.1.1 the dimension string on the right side should read “380 - 1220” for the metric instead of “390 - 1220.”
- Page 30: In Table 407.4.1 delete the reference to footnote 1 from the title line of the table. Footnote 1 should only be referenced in the bottom three rows under the column for “door clear opening width.”
- Page 68: In Figure 703.4.3 the dimension string on the left side for the “Distance between corresponding dots from one cell directly below” and the string along the top for “Distance between dots in adjacent cells” should be modified to measure to the corresponding dots in the adjacent cells. Figure should appear as shown below.



A117.1 2003 errata

10 September, 2007

Page 54: In Table 606.7, the second column in the first row should read as “0.5 inch (13 mm)”

Page 79: In the note to Table 802.9.2.2 the table number should be “802.9.2.2” instead of “802.8.9.”

A117.1 2003 errata


1 March, 2007

- Page 41: In Section 504.8.1 change the section heading to “**Illumination level.**”
- Page 41: In Section 504.8.1 in the third line, change the word “luminance” to be “illuminance.” The sentence should read “.....10 foot-candles (108 lux) of illuminance measured at.....”
- Page 41: In Section 504.8.2 in the third line, change the word “luminance” to be “illuminance.” The sentence should read “.....stairway lighting so the illuminance level required by.....”
- Page 44: In Section 506 add a new section number and heading of “**Section 506.1 General**”. The section would then read:
- Section 506 Windows**
Section 506.1 General. Accessible windows shall have operable parts complying with Section 309.
- Page 51: In Figures 604.8.5 (a), 604.8.5 (b) and 604.8.5 (c) delete the word “min” from the 6 inch toe clearance dimension string.
- Page 79: In Table 802.10 revise the heading of the second column to be “Minimum required number of dispersed locations.”

A117.1 2003 errata

13 December, 2005

- Page VI: In the third line of the last paragraph, the reference should be to the "ICC A117.1-2003" instead of to the "ICC 300-2002."
- Page IX: The number of professional members on the committee is 13 instead of 8. This also results in a total of 43 members instead of 38.
- Page 2: The figure should be labeled as "Fig. 104.3" instead of "Fig 104.2."
- Page 7: Figure 302.2 should have the dimension string modified so that it only measures the height of the carpet pile and does not include the backing/pad. Figure should appear as shown below.



- Page 16: In Figure 403.5.1(a) the dimension string on the left side should read "48 Min" instead of "48 Max."
- Page 54: In section 607.4 exception 2, the reference should be to section "1003.11.4" instead of "1003.11.9."
- Page 57: In Figure 608.2.1, delete the word "min" from the dimension string at the top of the figure. The dimension string should read "36" instead of "36 min."
- Page 57: In section 608.3 exception 2, the reference should be to section "1003.11.4" instead of "1003.11.9."
- Page 59: In section 608.4 exception 2, the reference should be to section "1003.11.4" instead of "1003.11.9."
- Page 90: In section 1003.3.2, the exception should reference ASections 1003.11.5 through 1003.11.9" instead of "Section 1003.11."

Page 91: In section 1003.11.1 the reference in the second line should be to section "1003.11.4" instead of to section "1003.11.9."

Page 95: In figure 1003.12.4, delete the dimension string which measures the bowl depth of the sink and the "6-1/2 max" dimension which is tied with it.